Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L3	0	(resistance near welding near electrode) and ((pre near form) or (green near compact)) and (sinter or sintering) and (inert near atmoshere)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:36
L2	0	(resistance near welding near electrode) and (sinter or sintering) and (inert near atmoshere)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:35
L3	154121	"219"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:34
L4	7.	(resistance near welding near electrode) and (sinter or sintering) and (inert near atmosphere)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:40
L5	2	(resistance near welding near electrode) and ((pre near form) or (green near compact)) and (sinter or sintering) and (inert near atmosphere)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:36
L6	13	I3 and (resistance near welding near electrode) and (sinter or sintering)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:42
L7	0	I3 and (resistance near welding near electrode) and (thermoforming or (semi near solid))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:43
L8	37	I3 and (resistance near welding near electrode) and (densif\$* or compressive or argon or xenon or hydrogen)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:44
L9	37	I3 and (resistance near welding near electrode) and (densif\$9 or compressive or argon or xenon or hydrogen)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/05/05 11:46